UNIVERSITY OF CAMBRIDGE INTERNATIONAL EXAMINATIONS General Certificate of Education Ordinary Level

METALWORK 6040/02

Paper 2 Practical Test

October/November 2006

3 hours

Additional Materials: As listed in the Instructions to Supervisors

READ THESE INSTRUCTIONS FIRST
Please see page 2.
All dimensions are in millimetres unless stated otherwise.

This document consists of 4 printed pages and 2 blank pages.



From the materials supplied you are to make the HAND VICE shown in the drawings.

You will be required to add further shaping to Part 5 as stated in the Working Procedures below.

All dimensions are in millimetres.

The following materials are supplied:

- Part 1 One piece BDMS $12 \times 12 \times 100$ long. Both ends squared.
- Part 2 One piece BDMS 12 × 12 × 40 long. Both ends squared.
- Part 3 One piece BDMS \emptyset 12 × 50 long, prepared prior to the examination.
- Part 4 One piece BDMS $\emptyset6 \times 50$ long, prepared prior to the examination.
- Part 5 One piece BDMS 10 x 2 x 23 long.
- Part 6 One piece BDMS 25 x 3 x 88 long. One end square.

One bag in which to enclose work.

Two tie-on labels.

Notes

Working Procedures

- A Part 5 should be shaped so that it is comfortable to hold.
- B After shaping, Part 5 is silver soldered to Part 3.
- C Part 4 is riveted into Part 2 and the joint filed flat.
- D Part 6 should be bent to 90° on the line shown using the former provided. The end with the 12 mm square hole should be held in the vice against the former.

General Notes

- A second supply of material is **not** allowed. If you make a mistake do your best to work as near to the dimensions given in the drawing as possible.
- Any dimensions omitted are left to your discretion.
- Attempt to complete all the work but remember that a partly completed piece of work of good quality may gain more marks than one which is complete but inaccurate or poorly finished.
- Clean up all parts by draw filing. Emery cloth or similar must not be used.
- Write your name and examination number on the labels supplied, attach one to your work and the other to the bag in which your work is enclosed. Put into the bag all worked and unworked materials, with the exception of waste.

BLANK PAGE

FOLD OUT THIS PAGE

BLANK PAGE

Permission to reproduce items where third-party owned material protected by copyright is included has been sought and cleared where possible. Every reasonable effort has been made by the publisher (UCLES) to trace copyright holders, but if any items requiring clearance have unwittingly been included, the publisher will be pleased to make amends at the earliest possible opportunity.

University of Cambridge International Examinations is part of the University of Cambridge Local Examinations Syndicate (UCLES), which is itself a department of the University of Cambridge.